


CV AKAGI

The AKAGI under attack at Midway. The location of the island on the port side is unusual in Japanese carriers.



CV KAGA

ONI 41-42 Recco Supplement No. 1 June 1943 3

The KAGA just before her destruction at Midway. Note the distinctive deck markings, characteristic of Japanese carriers, and the flight deck tapering toward the bow. The turning diameter as indicated by the arrow is approximately 1,100 yards.

