



KNOTS	RPM	KNOTS	RPM	KNOTS	RPM	KNOTS	RPM
34	417		300		200		100
	375		275		175		75
	350		250		150		50
	325		225		125		25

[388] ONI 41-42


30°




45°



270°



340°



350°



355°

