




MAX WOCHER & SON, CINCINNATI, O.




D/..1063




D/..1064



D/..1070



D/..1130



D/..1362

- D/..1063. **Ampere-meter**, mounted on swinging stand, graduated from 0 to 50 amperes, polished brass or nickel-plated \$25 00
- *D/..1063a. **Ampere-meter**, same as above, but without stand..... 20 00
- *D/..1063b. **Volt-meter**, without stand 25 00
- D/..1064. **Portable storage battery** for cautery work (6 volts, 35 amperes) and illumination (12 volts, 35 amperes)..... 50 00
- D/..1066. **Vetter current tap**, cords and 50 c. p. lamp for re-charging..... 1 00
- D/..1070. **Portable dip battery** for cautery and illuminating work..... 30 00
- D/..1130. **Baird's phimosi forceps**, 3 sizes 2 50
- D/..1362. **Berger's urethral irrigator**, for Janet's method, metal 1 25

ALL INSTRUMENTS BEARING THE K.-S. CO.'S



TRADE MARK ARE SOLD UNDER GUARANTEE.

MALE URETHRAL INSTRUMENTS.