

Cook, Horner & Co.

MANUFACTURERS AND DEALERS IN

Plumbers', Machinists' and Mill Supplies.

HYDRAULIC AND STEAM ENGINEERS,

Cor. Baltimore and Howard Streets.



Baltimore, Jan 22 1890

Mr. Elias Carr

Old Spruce St. B.

Dear Sir

Your valued favor of the 18. inst
to hand and contents carefully
noted will say in reply it is impossible
to repair old ones in place and they
will have to be removed and new
Fuller cocks soldered in lead pipe
or if you cannot do this you
can saw old ones off near the
solder joint and cut an iron
pipe thread on first in lead pipe
and then screw new spicket
on them with couplings as per sketch



this is the only way it can be done without plumber
cut off and put iron pipe thread on

Crook, Horner & Co.

MANUFACTURERS AND DEALERS IN

Plumbers', Machinists' and Mill Supplies.

HYDRAULIC AND STEAM ENGINEERS,

Cor. Baltimore and Howard Streets.

#2

Baltimore, 18

In case you should conclude to cut
off the spickgots you will send
us size of thread you put on
the piece and then we can send
you spickgots with the proper
couplings to suit

Yours Respectfully
Edward D. Crook
1. 24. 1882