



[60]

RANGER (CV)



Photos taken 1-6-43. Notice the numerous AAMG positions and open 5-inch gun mounts flanking the flight deck. Also prominent in these views is the characteristic broken freeboard.

